





数据接口




2032 电池




118-020-11




单位: mm



内径测量尺寸=读数+20mm



外径测量

内径测量
(测量尺寸>20mm)

| 货号 | 量程 | 精度 | a | c | h |
|------------|----------------|---------|----|----|-----|
| 118-012-11 | 0-300mm/0-12" | ±0.04mm | 18 | 24 | 100 |
| 118-012-12 | 0-300mm/0-12" | ±0.05mm | 18 | 24 | 150 |
| 118-012-13 | 0-300mm/0-12" | ±0.05mm | 18 | 24 | 200 |
| 118-020-11 | 0-500mm/0-20" | ±0.05mm | 18 | 24 | 100 |
| 118-020-12 | 0-500mm/0-20" | ±0.06mm | 18 | 24 | 150 |
| 118-020-13 | 0-500mm/0-20" | ±0.06mm | 24 | 32 | 200 |
| 118-020-14 | 0-500mm/0-20" | ±0.08mm | 24 | 42 | 300 |
| 118-024-11 | 0-600mm/0-24" | ±0.05mm | 18 | 24 | 100 |
| 118-024-12 | 0-600mm/0-24" | ±0.06mm | 18 | 24 | 150 |
| 118-024-13 | 0-600mm/0-24" | ±0.06mm | 24 | 32 | 200 |
| 118-024-15 | 0-600mm/0-24" | ±0.08mm | 24 | 42 | 300 |
| 118-040-11 | 0-1000mm/0-40" | ±0.08mm | 24 | 32 | 150 |
| 118-040-12 | 0-1000mm/0-40" | ±0.08mm | 24 | 32 | 200 |
| 118-040-13 | 0-1000mm/0-40" | ±0.10mm | 24 | 42 | 300 |
| 118-060-11 | 0-1500mm/0-60" | ±0.11mm | 24 | 42 | 150 |
| 118-080-11 | 0-2000mm/0-80" | ±0.14mm | 24 | 42 | 150 |

- ◆ 分辨率: 0.01mm/0.0005"
- ◆ 按键功能: 开关机, 置零, 公英制转换, 绝对/相对测量, 预置初始值
- ◆ 带数据输出(数据线货号:100-15)
- ◆ 不锈钢尺身