



测厚规


434



- ◆ 按键: 开/关, 置零, 公/英制转换
- ◆ 自动关机



单位: mm



货号	量程	分辨率	精度
434-001-11	0-25mm/0-1"	0.01mm/0.0005"	±0.03mm